



## Flat Rate Repair Price List

The following table reflects the repair rates for the particular modules replaced. Labor is included in the price. Total cost of repair will depend on boards replaced.

If a defective LBT is found, a Tracker or POTS board may have to be replaced also if the 9522 is defective and an upgrade to the 9522A is required. The 9522 is no longer available from Iridium. In this situation the cost would be the LBT plus the board replaced.

Description	Part Number	Cost to Customer (Labor Included)
Rabbit Module	1616-603-02	\$500.00
IDT Module Board (Aviation)	1616-600-05	\$900.00
IDT Module Board (Marine)	1616-600-06	\$900.00
Tracker 2 Module Board	1616-602-02	\$900.00
LBT	1616-695-22A	\$1300.00
SatTalk 2	1616-500-03	\$400.00
SatTalk 3	1616-510-03	\$600.00
SOP Dialer		\$200.00
MMU Display	1616-055-0001	\$350.00
MMU Processor	1616-055-0002	\$350.00
Power Supply Module	1616-601-03	\$250.00
Labor Charges per hour		\$100.00
Configuration Module	1616-905-01	NA
SIM/Config Module	1616-905-02	\$350.00
Upgrade from and old unit to an A model (ie 1616-050-03 to a 1616-050-03A)		Customer is given a credit of \$1500.00 (core credit) towards the purchase of a new unit.

**Shipping cost will be added to all repairs.**

**Items being estimated and then not repaired will be billed a \$100 estimate fee.**

**Labor charges will apply whenever there is not a specific part to be replaced, i.e. alignment of an article. Labor is a minimum of 1 hour.**