



SOFTWARE BULLETIN

Sky Connect LLC

SW Bulletin SW2009-001

Category: Aviation

Topic: MMU II software bug with Version 1.2

Effective Date: June 18, 2009

A problem has been discovered which **may** affect dialing strings in version 1.2 of the MMU II software. The software is adding an additional number of digits to the end of some phone numbers due to a cache file containing “garbage”. A new version of the software has been released that will correct this issue and clear the cache file of any “garbage” left behind.

CORRECTION: Return the unit to Sky Connect for a reload of the operating software. If you have the ability to load your own software contact Tech support for instructions on how to download the needed software from our FTP site.

WARRANTY CONSIDERATION: Sky Connect will repair, free of charge, all units that have this problem.