

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

Number SR02569NY

This certificate issued to Sky Connect LLC
40070 Cane Street, #600
Slidell, LA 70461

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: H9EU
Make: Eurocopter France
Model: AS 350 B, B1, B2, B3, BA, C, D, D1

Description of Type Design Change:

The installation of a Sky Connect Tracking System to be done in accordance with approved Avionics Design Services Ltd. *Master Drawing List MDL07094, Revision A, dated January 10, 2008, or later FAA approved revision.

Limitations and Conditions:

1. Maintenance must be performed in accordance with *Avionics Design Services Ltd. Instructions for Continued Airworthiness ICA07094-1, Rev A, dated December 19, 2007 or later FAA accepted revisions.
2. Operation must be performed in accordance with *Avionics Services Ltd. Flight Manual Supplement FMS07094-1, Rev A, dated July 2, 2008, or later FAA approved revision.
3. The installer must determine whether this design change is compatible with previously approved modifications.
4. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.
5. *Those documents were initially approved/accepted by Transport Canada under the Bilateral with the US.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: December 11, 2007

Date reissued: April 15, 2009

Date of issuance: October 06, 2008

Date amended:



By direction of the Administrator

For Anthony Socias (Signature)
Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.