

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number SR02712NY

This certificate issued to Avionics Design Services Ltd.
230 Aberdeen Boulevard, Unit 1 and 2
Midland, Ontario
L4R 5N4, Canada

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 6 of the Civil Air Regulations.

Original Product -- Type Certificate Number : H2SW

Make : Bell

Model : 407

Description of Type Design Change :

The installation of a Sky Connect Satcom/Tracking System must be performed in accordance with Avionics Design Services Ltd. Master Drawing List No. MDL08055, Rev. E, Issue 1, dated April, 20, 2009 or later Transport Canada approved revision.

Limitations and Conditions :

1. Maintenance must be in accordance with the following documents:
 - a. Icarus Instruments Instructions for Continued Airworthiness Document No. DOC A2006-031-1, Rev. B, dated August 12, 2006, Transport Canada accepted April 1, 2009 or later Transport Canada accepted revision.
 - b. Document Change Notice No. DCN08055-1, Issue 3, dated April 20, 2009 or later Transport Canada approved revision.
2. Operation must be in accordance with Avionics Design Services Ltd. Rotorcraft Flight Manual Supplement No. FMS08055-1, Rev. N/C, approved April 1, 2009 or later Transport Canada approved revision.
3. The installer must determine whether this design change is compatible with previously approved modifications.
4. If the holder agrees to permit another person to use the certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : April 7, 2009

Date reissued :

Date of issuance : July 7, 2009

Date amended :



By direction of the Administrator

[Signature]
(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.